

Fig. 1




Fig. 2a





Fig. 2b








Fig. 5




Fig. 6




Fig. 7




Fig. 8




Fig. 9




Fig. 10




Fig. 11




Fig. 12




Fig. 13




Fig. 14




Fig. 15




Fig. 16




Fig. 17




Fig. 18

Claims ID# 20000307135816000127

Dealership Mashni Motor Company

P & A Code 1

Submitted By Dave G Park

Reviewer Jeremy Willard

Date 3/7/00 1:57 PM EST

Status New

RO Number 563214

VIN 1ZWHT61L9X5650604

Make

Model

Model Year

KILOMETERS 15632

NEW

Repair line item 1

Claim Status Approved

ACES Code P17JW

Symptom Code ☒

Customer Waiting ☐

Parts on Hand ☐

Paint ☐

Description

TP> Customer reports broken cup holder.
Holder should be replaced. Thanks! Dave.
JW> YOUR APPROVED TO REPLACE CUP HOLDER.
THANKS, JEREMY 1436
DP>

Digital Imaging




Camera Docked

Receive Claimset

Next

Reset

Send Claimset

120

130

140

150

MPH

12:54

015632

120

130

140

150

MPH

12:54

015632

3/8/2000 1:44am

Fig. 19a

Claimset ID# 20000307135616000127

Dealership Mashnt Motor Company

P & A Code 1

Submitted By Dave Park

Reviewer Jeremy Willard

Date 3/7/00 1:57 PM EST

Status New

RO Number 563214

VIN 1ZWHT61L9X5650604

Make

Model

Model Year

Kilometers 15632

Repair line item 1

Claim Status Approved

ACES Code P17JW

Symptom Code

Customer Waiting ☒

Parts on Hand ☐

Paint ☐

Description

DP> Customer reports broken cup holder.
Holder should be replaced Thanks! Dave
JW> YOUR APPROVED TO REPLACE CUP HOLDER
THANKS, JEREMY 1436
DP>

Claimset ID# 20000307135616000127

Dealership Mashnt Motor Company

P & A Code 1

Submitted By Dave Park

Reviewer Jeremy Willard

Date 3/7/00 1:57 PM EST

Status New

RO Number 563214

VIN 1ZWHT61L9X5650604

Make

Model

Model Year

Kilometers 15632

Repair line item 1

Claim Status Approved

ACES Code P17JW

Symptom Code

Customer Waiting ☒

Parts on Hand ☐

Paint ☐

Description

DP> Customer reports broken cup holder.
Holder should be replaced Thanks! Dave
JW> YOUR APPROVED TO REPLACE CUP HOLDER
THANKS, JEREMY 1436
DP>

Claimset ID# 20000307135616000127

Dealership Mashnt Motor Company

P & A Code 1

Submitted By Dave Park

Reviewer Jeremy Willard

Date 3/7/00 1:57 PM EST

Status New

RO Number 563214

VIN 1ZWHT61L9X5650604

Make

Model

Model Year

Kilometers 15632

Repair line item 1

Claim Status Approved

ACES Code P17JW

Symptom Code

Customer Waiting ☒

Parts on Hand ☐

Paint ☐

Description

DP> Customer reports broken cup holder.
Holder should be replaced Thanks! Dave
JW> YOUR APPROVED TO REPLACE CUP HOLDER
THANKS, JEREMY 1436
DP>

Claimset ID# 20000307135616000127

Dealership Mashnt Motor Company

P & A Code 1

Submitted By Dave Park

Reviewer Jeremy Willard

Date 3/7/00 1:57 PM EST

Status New

RO Number 563214

VIN 1ZWHT61L9X5650604

Make

Model

Model Year

Kilometers 15632

Repair line item 1

Claim Status Approved

ACES Code P17JW

Symptom Code

Customer Waiting ☒

Parts on Hand ☐

Paint ☐

Description

DP> Customer reports broken cup holder.
Holder should be replaced Thanks! Dave
JW> YOUR APPROVED TO REPLACE CUP HOLDER
THANKS, JEREMY 1436
DP>

Claimset ID# 20000307135616000127

Dealership Mashnt Motor Company

P & A Code 1

Submitted By Dave Park

Reviewer Jeremy Willard

Date 3/7/00 1:57 PM EST

Status New

RO Number 563214

VIN 1ZWHT61L9X5650604

Make

Model

Model Year

Kilometers 15632

Repair line item 1

Claim Status Approved

ACES Code P17JW

Symptom Code

Customer Waiting ☒

Parts on Hand ☐

Paint ☐

Description

DP> Customer reports broken cup holder.
Holder should be replaced Thanks! Dave
JW> YOUR APPROVED TO REPLACE CUP HOLDER
THANKS, JEREMY 1436
DP>

Claimset ID# 20000307135616000127

Dealership Mashnt Motor Company

P & A Code 1

Submitted By Dave Park

Reviewer Jeremy Willard

Date 3/7/00 1:57 PM EST

Status New

RO Number 563214

VIN 1ZWHT61L9X5650604

Make

Model

Model Year

Kilometers 15632

Repair line item 1

Claim Status Approved

ACES Code P17JW

Symptom Code

Customer Waiting ☒

Parts on Hand ☐

Paint ☐

Description

DP> Customer reports broken cup holder.
Holder should be replaced Thanks! Dave
JW> YOUR APPROVED TO REPLACE CUP HOLDER
THANKS, JEREMY 1436
DP>

Fig. 19b